

CLAMPING TECHNOLOGY

Product Index

| Model No. | Page | Model No. | Page | Model No. | Page |
|---------------|-------------|----------------|-----------|--------------|-----------|
| 035-125-190 | MC-PSC-32 | 2002-U-LS-BLK | MC-VHD-3 | 2027-UR | MC-HHD-7 |
| 035-125-290 | MC-PSC-32 | 2002-U207 | MC-VHD-3 | 202943 | MC-ACC-4 |
| 035-132-190 | MC-PSC-32 | 2002-UB | MC-VHD-3 | 202943-M | MC-ACC-4 |
| 035-132-290 | MC-PSC-32 | 2002-UB-LS-BLK | MC-VHD-3 | 205-S | MC-HHD-19 |
| 035-140-190 | MC-PSC-32 | 2002-UBR | MC-VHD-3 | 205-SB | MC-HHD-19 |
| 035-140-290 | MC-PSC-32 | 2002-UR | MC-VHD-3 | 205-SL | MC-HHD-19 |
| 035-150-190 | MC-PSC-32 | 2002-UR207 | MC-VHD-3 | 205-SR | MC-HHD-19 |
| 035-150-290 | MC-PSC-32 | 2002115-E | MC-ACC-6 | 205-SSS | MC-HHD-19 |
| 035-225-190 | MC-PSC-32 | 2007-S | MC-VHD-7 | 205-U | MC-HHD-19 |
| 035-225-290 | MC-PSC-32 | 2007-SB | MC-VHD-7 | 205-UB | MC-HHD-19 |
| 035-232-190 | MC-PSC-32 | 2007-SBR | MC-VHD-7 | 205-UL | MC-HHD-19 |
| 035-232-290 | MC-PSC-32 | 2007-SR | MC-VHD-7 | 205-UR | MC-HHD-19 |
| 035-240-190 | MC-PSC-32 | 2007-U | MC-VHD-7 | 205-USS | MC-HHD-19 |
| 035-240-290 | MC-PSC-32 | 2007-U-LS-BLK | MC-VHD-7 | 205203 | MC-ACC-4 |
| 035-250-190 | MC-PSC-32 | 2007-UB | MC-VHD-7 | 205203-M | MC-ACC-4 |
| 035-250-290 | MC-PSC-32 | 2007-UB-LS-BLK | MC-VHD-7 | 205208-M | MC-ACC-2 |
| 036-551-01 | MC-PSC-35 | 2007-UBR | MC-VHD-7 | 205943 | MC-ACC-4 |
| 036-551-02 | MC-PSC-35 | 2007-UR | MC-VHD-7 | 205943-M | MC-ACC-4 |
| 036-630-01 | MC-PSC-35 | 2007115-E | MC-ACC-6 | 206-HSS | MC-HHD-29 |
| 036-630-02 | MC-PSC-35 | 2007208-M | MC-ACC-2 | 206-SS | MC-HHD-29 |
| 036-787-01 | MC-PSC-35 | 201-TU | MC-VHD-11 | 207-L | MC-VHD-17 |
| 036-787-02 | MC-PSC-35 | 201-U | MC-VHD-11 | 207-LB | MC-VHD-17 |
| 039-101-000DE | MC-HYD-13 | 201-UB | MC-VHD-11 | 207-LBR | MC-VHD-17 |
| 039-104-000DE | MC-HYD-13 | 201-USS | MC-VHD-11 | 207-LR | MC-VHD-17 |
| 051-112-160 | MC-HYD-4 | 2010-S | MC-VHD-9 | 207-S | MC-VHD-17 |
| 051-131-160 | MC-HYD-4 | 2010-SB | MC-VHD-9 | 207-SB | MC-VHD-17 |
| 051-137-180 | MC-HYD-4 | 2010-SBR | MC-VHD-9 | 207-SF | MC-VHD-17 |
| 051-150-160 | MC-PSC-36 | 2010-SR | MC-VHD-9 | 207-TU | MC-VHD-17 |
| 051-187-160 | MC-PSC-36, | 2010-U | MC-VHD-9 | 207-TUL | MC-VHD-17 |
| | MC-HYD-4 | 2010-UB | MC-VHD-9 | 207-U | MC-VHD-17 |
| 051-225-160 | MC-PSC-36 | 2010-UBR | MC-VHD-9 | 207-U-L | MC-VHD-17 |
| 051-250-160 | MC-PSC-36, | 2010-UR | MC-VHD-9 | 207-U-L-BLK | MC-VHD-17 |
| | MC-HYD-4 | 2010115-E | MC-ACC-6 | 207-UB | MC-VHD-17 |
| 052-112-160 | MC-HYD-4 | 201208 | MC-ACC-2 | 207-UB-L | MC-VHD-17 |
| 052-131-160 | MC-HYD-4 | 201208-M | MC-ACC-2 | 207-UB-L-BLK | MC-VHD-17 |
| 052-137-180 | MC-HYD-4 | 2013-U | MC-HHD-3 | 207-UF | MC-VHD-17 |
| 052-187-160 | MC-HYD-4 | 2013-U-LS-BLK | MC-HHD-3 | 207-UL | MC-VHD-17 |
| 052-250-160 | MC-HYD-4 | 2013-UR | MC-HHD-3 | 207-ULB | MC-VHD-17 |
| 1000 | PC-PPC-65 | 2013208-M | MC-ACC-2 | 207-UR | MC-VHD-17 |
| 1001 | PC-PPC-65 | 2017-U | MC-HHD-5 | 207-USS | MC-VHD-17 |
| 10010100 | PC-PPC-65 | 2017-U-LS-BLK | MC-HHD-5 | 207105 | MC-ACC-6 |
| 1005133-MR | PC-PPC-65 | 2017-UR | MC-HHD-5 | 207105-M | MC-ACC-6 |
| 1005134-MR | PC-PPC-65 | 201943 | MC-ACC-4 | 207203 | MC-ACC-4 |
| 102111 | MC-ACC-6 | 201943-M | MC-ACC-4 | 207203-M | MC-ACC-4 |
| 102208 | MC-ACC-2 | 202 | MC-VHD-13 | 207206 | MC-ACC-3 |
| 102911 | MC-ACC-6 | 202-B | MC-VHD-13 | 207206-M | MC-ACC-3 |
| 105106 | MC-ACC-6 | 202-SS | MC-VHD-13 | 207209 | MC-ACC-3 |
| 105203 | MC-ACC-4 | 202-T | MC-VHD-13 | 207305 | MC-VHD-17 |
| 105208 | MC-ACC-2 | 202-TU | MC-VHD-13 | 207426-Q | MC-ACC-10 |
| 105906 | MC-ACC-6 | 202-U | MC-VHD-13 | 207943 | MC-ACC-4 |
| 12/100 | MC-VSC-4 | 202-U-L | MC-VHD-13 | 207943-M | MC-ACC-4 |
| 12/200 | MC-VSC-4 | 202-U-L-BLK | MC-VHD-13 | 210-S | MC-VHD-21 |
| 12/300 | MC-VSC-4 | 202-UB | MC-VHD-13 | 210-SB | MC-VHD-21 |
| 1200 | MC-PTC-29 | 202-UB-L | MC-VHD-13 | 210-SR | MC-VHD-21 |
| 1200-E | MC-PTC-29 | 202-UB-L-BLK | MC-VHD-13 | 210-TU | MC-VHD-21 |
| 16/100 | MC-VSC-4, 7 | 202-UL | MC-VHD-13 | 210-U | MC-VHD-21 |
| 16/200 | MC-VSC-4, 7 | 202-USS | MC-VHD-13 | 210-UB | MC-VHD-21 |
| 16/300 | MC-VSC-4, 7 | 202203 | MC-ACC-4 | 210-UR | MC-VHD-21 |
| 2002-S | MC-VHD-3 | 202208 | MC-ACC-2 | 210-USS | MC-VHD-21 |
| 2002-SB | MC-VHD-3 | 202208-M | MC-ACC-2 | 210114 | MC-ACC-6 |
| 2002-SBR | MC-VHD-3 | 202305 | MC-VHD-13 | 210114-M | MC-ACC-6 |
| 2002-SR | MC-VHD-3 | 2027-U | MC-HHD-7 | 210203 | MC-ACC-4 |
| 2002-U | MC-VHD-3 | 2027-U-LS-BLK | MC-HHD-7 | 210203-M | MC-ACC-4 |

CLAMPING TECHNOLOGY

Product Index

| Model No. | Page | Model No. | Page | Model No. | Page |
|---------------|-----------|-----------|-----------|--------------|---------------|
| 210206 | MC-ACC-3 | 235-UR | MC-HHD-25 | 307208-M | MC-ACC-2 |
| 210206-M | MC-ACC-3 | 235-USS | MC-HHD-25 | 309-U | MC-HHD-27 |
| 210208 | MC-ACC-3 | 235106 | MC-ACC-6 | 309-UR | MC-HHD-27 |
| 210209 | MC-ACC-3 | 235110 | MC-ACC-5 | 309-USS | MC-HHD-27 |
| 210440-Q | MC-ACC-10 | 235119 | MC-ACC-5 | 311 | MC-PAL-22 |
| 213-U | MC-HHD-9 | 235208 | MC-ACC-2 | 317-S | MC-VHD-37 |
| 213-U-L | MC-HHD-9 | 235208-M | MC-ACC-2 | 317-U | MC-VHD-37 |
| 213-U-LS-BLK | MC-HHD-9 | 235219 | MC-ACC-5 | 323 | MC-PAL-9 |
| 213-UB | MC-HHD-9 | 235219-M | MC-ACC-5 | 323-R | MC-PAL-9 |
| 213-UB-L | MC-HHD-9 | 235319 | MC-ACC-5 | 323-RSS | MC-PAL-9 |
| 213-UB-LS-BLK | MC-HHD-9 | 235906 | MC-ACC-6 | 323-SS | MC-PAL-9 |
| 213-USS | MC-HHD-9 | 237-U | MC-HHD-15 | 323215 | MC-PAL-12 |
| 213208 | MC-ACC-3 | 237-USS | MC-HHD-15 | 323215-M-100 | MC-PAL-12 |
| 213208-M | MC-ACC-2 | 237943 | MC-ACC-4 | 323215-M-25 | MC-PAL-12 |
| 213208-M-L | MC-ACC-2 | 237943-M | MC-ACC-4 | 323215-M-50 | MC-PAL-12 |
| 215-S | MC-HHD-21 | 240203 | MC-ACC-4 | 323915 | MC-PAL-12 |
| 215-U | MC-HHD-21 | 240203-M | MC-ACC-4 | 323915-M-100 | MC-PAL-12 |
| 215-UB | MC-HHD-21 | 240208 | MC-ACC-2 | 323915-M-25 | MC-PAL-12 |
| 215-USS | MC-HHD-21 | 240208-M | MC-ACC-2 | 323915-M-50 | MC-PAL-12 |
| 215105 | MC-ACC-6 | 245-U | MC-HHD-17 | 324 | MC-PAL-18 |
| 215119 | MC-ACC-5 | 245943 | MC-ACC-4 | 324-R | MC-PAL-18 |
| 215208 | MC-ACC-2 | 245943-M | MC-ACC-4 | 324-RSS | MC-PAL-18 |
| 215208-M | MC-ACC-2 | 247-S | MC-VHD-23 | 324-SS | MC-PAL-18 |
| 215219 | MC-ACC-5 | 247-U | MC-VHD-23 | 324-ZB1 | MC-PAL-12, 21 |
| 215219-M | MC-ACC-5 | 247-UB | MC-VHD-23 | 324215 | MC-PAL-21 |
| 215319 | MC-ACC-5 | 247109 | MC-ACC-6 | 324215-M-100 | MC-PAL-21 |
| 215905 | MC-ACC-6 | 247110 | MC-ACC-6 | 324215-M-25 | MC-PAL-21 |
| 217-U | MC-HHD-11 | 247110-M | MC-ACC-6 | 324215-M-50 | MC-PAL-21 |
| 217-U-L | MC-HHD-11 | 247208 | MC-ACC-2 | 324915 | MC-PAL-21 |
| 217-U-L-BLK | MC-HHD-11 | 247208-M | MC-ACC-2 | 324915-M-100 | MC-PAL-21 |
| 217-U-LS-BLK | MC-HHD-11 | 247909 | MC-ACC-6 | 324915-M-25 | MC-PAL-21 |
| 217-UB | MC-HHD-11 | 250121 | MC-ACC-6 | 324915-M-50 | MC-PAL-21 |
| 217-UB-L | MC-HHD-11 | 250203 | MC-ACC-4 | 325 | MC-SAP-2 |
| 217-UB-L-BLK | MC-HHD-11 | 250206 | MC-ACC-3 | 325-SS | MC-SAP-2 |
| 217-UB-LS-BLK | MC-HHD-11 | 250206-M | MC-ACC-3 | 325203 | MC-ACC-4 |
| 217-USS | MC-HHD-11 | 267-S | MC-VHD-23 | 32MM | MC-VSC-11 |
| 22/100 | MC-VSC-4 | 267-U | MC-VHD-23 | 330 | MC-PAL-5 |
| 22/200 | MC-VSC-4 | 267102 | MC-ACC-6 | 330-SS | MC-PAL-5 |
| 22/300 | MC-VSC-4 | 267203-M | MC-ACC-4 | 330-ZB1 | MC-PAL-8,12 |
| 220203 | MC-ACC-4 | 267208 | MC-ACC-2 | 330215 | MC-PAL-8 |
| 220203-M | MC-ACC-4 | 267902 | MC-ACC-6 | 330215-M-100 | MC-PAL-8 |
| 225-U | MC-HHD-23 | 301 | MC-PAL-22 | 330215-M-25 | MC-PAL-8 |
| 225-UB | MC-HHD-23 | 301-SS | MC-PAL-22 | 330215-M-50 | MC-PAL-8 |
| 225-UBSS | MC-HHD-23 | 3011 | MC-PAL-23 | 330915 | MC-PAL-8 |
| 225-UR | MC-HHD-23 | 3031 | MC-PAL-3 | 330915-M-100 | MC-PAL-8 |
| 225-USS | MC-HHD-23 | 3031-R | MC-PAL-3 | 330915-M-25 | MC-PAL-8 |
| 225119 | MC-ACC-5 | 3031-SS | MC-PAL-3 | 330915-M-50 | MC-PAL-8 |
| 225208 | MC-ACC-2 | 3031-RSS | MC-PAL-3 | 331 | MC-PAL-9 |
| 225208-M | MC-ACC-2 | 3031208 | MC-PAL-3 | 331-R | MC-PAL-9 |
| 225219 | MC-ACC-5 | 305-U | MC-HHD-27 | 331-RSS | MC-PAL-9 |
| 225219-M | MC-ACC-5 | 305-UR | MC-HHD-27 | 331-SS | MC-PAL-9 |
| 225319 | MC-ACC-5 | 305-USS | MC-HHD-27 | 331215 | MC-PAL-12 |
| 227-U | MC-HHD-13 | 3051 | MC-PAL-3 | 331215-M-100 | MC-PAL-12 |
| 227-U-L | MC-HHD-13 | 3051-R | MC-PAL-3 | 331215-M-25 | MC-PAL-12 |
| 227-U-L-BLK | MC-HHD-13 | 3051-SS | MC-PAL-3 | 331215-M-50 | MC-PAL-12 |
| 227-UB | MC-HHD-13 | 3051-RSS | MC-PAL-3 | 331915 | MC-PAL-12 |
| 227-UB-L | MC-HHD-13 | 3051208 | MC-PAL-3 | 331915-M-100 | MC-PAL-12 |
| 227-UB-L-BLK | MC-HHD-13 | 305203 | MC-ACC-4 | 331915-M-25 | MC-PAL-12 |
| 227-UB-LS-BLK | MC-HHD-13 | 305208 | MC-ACC-3 | 331915-M-50 | MC-PAL-12 |
| 227-USS | MC-HHD-13 | 305208-M | MC-ACC-2 | 334 | MC-PAL-18 |
| 229 | MC-VHD-41 | 307-U | MC-HHD-27 | 334-R | MC-PAL-18 |
| 235-U | MC-HHD-25 | 307-UR | MC-HHD-27 | 334-RSS | MC-PAL-18 |
| 235-UB | MC-HHD-25 | 307-USS | MC-HHD-27 | 334-SS | MC-PAL-18 |

CLAMPING TECHNOLOGY

Product Index

| Model No. | Page | Model No. | Page | Model No. | Page |
|--------------|---------------|--------------|---------------|-----------|-----------|
| 334-ZB1 | MC-PAL-18, 21 | 371215-M-50 | MC-PAL-8 | 482 | MC-SAP-7 |
| 334215 | MC-PAL-21 | 371915 | MC-PAL-8 | 484 | MC-SAP-7 |
| 334215-M-100 | MC-PAL-21 | 371915-M-100 | MC-PAL-8 | 486 | MC-SAP-7 |
| 334215-M-25 | MC-PAL-21 | 371915-M-25 | MC-PAL-8 | 491203 | MC-ACC-4 |
| 334215-M-50 | MC-PAL-21 | 371915-M-50 | MC-PAL-8 | 491203-M | MC-ACC-4 |
| 334915 | MC-PAL-21 | 374 | MC-PAL-18 | 501-B | MC-VHD-43 |
| 334915-M-100 | MC-PAL-21 | 374215 | MC-PAL-21 | 501-LB | MC-VHD-43 |
| 334915-M-25 | MC-PAL-21 | 374215-M-100 | MC-PAL-21 | 501501 | MC-VHD-46 |
| 334915-M-50 | MC-PAL-21 | 374215-M-25 | MC-PAL-21 | 501503 | MC-VHD-46 |
| 341 | MC-PAL-9 | 374215-M-50 | MC-PAL-21 | 503-MB | MC-VHD-43 |
| 341-R | MC-PAL-9 | 375 | MC-PAL-13 | 503-MBLSC | MC-VHD-43 |
| 341-RSS | MC-PAL-9 | 375-B | MC-PAL-13 | 503-MLB | MC-VHD-43 |
| 341-SS | MC-PAL-9 | 375-BR | MC-PAL-13 | 503-MBLSC | MC-VHD-43 |
| 341-ZB1 | MC-PAL-12 | 375-R | MC-PAL-13 | 503501 | MC-VHD-46 |
| 341215 | MC-PAL-12 | 375-ZB1 | MC-PAL-14, 21 | 503502 | MC-VHD-46 |
| 341215-M-100 | MC-PAL-12 | 375215 | MC-PAL-14 | 503503-L | MC-VHD-46 |
| 341215-M-25 | MC-PAL-12 | 375509 | MC-PAL-13, 18 | 505-MB | MC-VHD-43 |
| 341215-M-50 | MC-PAL-12 | 381 | MC-PAL-4 | 505-MBLSC | MC-VHD-43 |
| 341915 | MC-PAL-12 | 381-SS | MC-PAL-4 | 505-MLB | MC-VHD-43 |
| 341915-M-100 | MC-PAL-12 | 381-ZB1 | MC-PAL-4 | 505-MBLSC | MC-VHD-43 |
| 341915-M-25 | MC-PAL-12 | 381215 | MC-PAL-8 | 505501 | MC-VHD-46 |
| 341915-M-50 | MC-PAL-12 | 381215-M-100 | MC-PAL-8 | 505502 | MC-VHD-46 |
| 344 | MC-PAL-18 | 381215-M-25 | MC-PAL-8 | 505503-L | MC-VHD-46 |
| 344-R | MC-PAL-18 | 381215-M-50 | MC-PAL-8 | 506-MB | MC-VHD-43 |
| 344-RSS | MC-PAL-18 | 381915 | MC-PAL-8 | 506-MBLSC | MC-VHD-43 |
| 344-SS | MC-PAL-18 | 381915-M-100 | MC-PAL-8 | 506-MLB | MC-VHD-43 |
| 344-ZB1 | MC-PAL-18, 21 | 381915-M-25 | MC-PAL-8 | 506-MBLSC | MC-VHD-43 |
| 344215 | MC-PAL-21 | 381915-M-50 | MC-PAL-8 | 506501 | MC-VHD-46 |
| 344215-M-100 | MC-PAL-21 | 385 | MC-PAL-15 | 506502 | MC-VHD-46 |
| 344215-M-25 | MC-PAL-21 | 385-L | MC-PAL-15 | 506503-L | MC-VHD-46 |
| 344215-M-50 | MC-PAL-21 | 385-R | MC-PAL-15 | 507107 | MC-ACC-6 |
| 344915 | MC-PAL-21 | 385-RSS | MC-PAL-15 | 507206 | MC-ACC-3 |
| 344915-M-100 | MC-PAL-21 | 385-SS | MC-PAL-15 | 507206-M | MC-ACC-3 |
| 344915-M-25 | MC-PAL-21 | 385-ZB1 | MC-PAL-17 | 507208 | MC-ACC-2 |
| 344915-M-50 | MC-PAL-21 | 385102 | MC-PAL-15, 17 | 507208-M | MC-ACC-2 |
| 345 | MC-SAP-3 | 385215 | MC-PAL-17 | 507209 | MC-ACC-3 |
| 345-G | MC-SAP-3 | 385215-M-100 | MC-PAL-17 | 507907 | MC-ACC-6 |
| 351 | MC-PAL-4 | 385215-M-25 | MC-PAL-17 | 509208 | MC-ACC-3 |
| 351-B | MC-PAL-4 | 385215-M-50 | MC-PAL-17 | 5105 | MC-VHD-29 |
| 351-BSS | MC-PAL-4 | 385915 | MC-PAL-17 | 5110 | MC-VHD-29 |
| 351-R | MC-PAL-4 | 385915-M-100 | MC-PAL-17 | 5130 | MC-SLA-21 |
| 351-RSS | MC-PAL-4 | 385915-M-25 | MC-PAL-17 | 5130-B | MC-SLA-21 |
| 351-SS | MC-PAL-4 | 385915-M-50 | MC-PAL-17 | 5130-M | MC-SLA-21 |
| 351-ZB1 | MC-PAL-6 | 424 | MC-SAP-4 | 5130-MB | MC-SLA-21 |
| 351215 | MC-PAL-8 | 424-2 | MC-SAP-4 | 5131 | MC-SLA-21 |
| 351215-M-100 | MC-PAL-8 | 424107 | MC-ACC-5 | 5131-B | MC-SLA-21 |
| 351215-M-25 | MC-PAL-8 | 424208 | MC-ACC-2 | 5131-M | MC-SLA-21 |
| 351215-M-50 | MC-PAL-8 | 424208-M | MC-ACC-2 | 5131-MB | MC-SLA-21 |
| 351915 | MC-PAL-8 | 425 | MC-SAP-6 | 5133 | MC-SLA-21 |
| 351915-M-100 | MC-PAL-8 | 431 | MC-SAP-5 | 5133-B | MC-SLA-21 |
| 351915-M-25 | MC-PAL-8 | 431208 | MC-ACC-2 | 5133-M | MC-SLA-21 |
| 351915-M-50 | MC-PAL-8 | 431208-M | MC-ACC-2 | 5133-MB | MC-SLA-21 |
| 353-35 | MC-PAL-24 | 435 | MC-SAP-6 | 5150 | MC-SLA-23 |
| 353-65 | MC-PAL-24 | 441 | MC-SAP-4 | 5150-B | MC-SLA-23 |
| 353004 | MC-PAL-24 | 441-2 | MC-SAP-4 | 5150-M | MC-SLA-23 |
| 371 | MC-PAL-5 | 441203 | MC-ACC-4 | 5150-MB | MC-SLA-23 |
| 371-R | MC-PAL-5 | 461203 | MC-ACC-4 | 519208 | MC-ACC-3 |
| 371-RSS | MC-PAL-5 | 461203-M | MC-ACC-4 | 527 | MC-VHD-39 |
| 371-SS | MC-PAL-5 | 462 | MC-SAP-7 | 527-F | MC-VHD-39 |
| 371-ZB1 | MC-PAL-7 | 462-2 | MC-SAP-7 | 527203 | MC-ACC-4 |
| 371215 | MC-PAL-8 | 463 | MC-SAP-7 | 527208 | MC-ACC-2 |
| 371215-M-100 | MC-PAL-8 | 468206 | MC-ACC-3 | 528 | MC-VHD-31 |
| 371215-M-25 | MC-PAL-8 | 468206-M | MC-ACC-3 | 528-F | MC-VHD-31 |

CLAMPING TECHNOLOGY

Product Index

| Model No. | Page | Model No. | Page | Model No. | Page |
|-------------|-----------|------------|---------------|----------------|---------------|
| 52H-3E...50 | PC-PPC-53 | 610-M | MC-SLA-13 | 810158 | MC-PSC-40 |
| 52H-3E...63 | PC-PPC-53 | 614-M | MC-SLA-29 | 810169 | MC-PSC-40 |
| 5305 | MC-HHD-31 | 615 | MC-SLA-14 | 810170 | MC-PSC-40 |
| 5310 | MC-HHD-31 | 620 | MC-SLA-15 | 810171 | MC-PSC-40 |
| 533-L | MC-VHD-33 | 620-M | MC-SLA-15 | 810173 | MC-PSC-40 |
| 533-LB | MC-VHD-33 | 624 | MC-SLA-25 | 810174 | MC-PSC-40 |
| 535-L | MC-VHD-33 | 624-MM | MC-SLA-25 | 8115 | MC-PSC-19 |
| 535-LB | MC-VHD-33 | 624-SS | MC-SLA-25 | 8116 | MC-PSC-19 |
| 548 | MC-VHD-32 | 624106-M | MC-SLA-28 | 812-U | MC-PTC-3 |
| 558 | MC-VHD-35 | 630 | MC-SLA-16 | 817-S | MC-PTC-21 |
| 578 | MC-VHD-32 | 630-M | MC-SLA-16 | 817-SE | MC-PTC-21 |
| 5905 | MC-VHD-27 | 630-MR | MC-SLA-16 | 817-U | MC-PTC-21 |
| 5910 | MC-VHD-27 | 630-R | MC-SLA-16 | 817-UE | MC-PTC-21 |
| 5915 | MC-VHD-27 | 640 | MC-SLA-17 | 81L-12-1.... | PC-PPC-3 |
| 6001 | MC-SLA-3 | 640-M | MC-SLA-17 | 81L-16-1.... | PC-PPC-3 |
| 6001-M | MC-SLA-3 | 640-MR | MC-SLA-17 | 81L-20-1.... | PC-PPC-3 |
| 6001-MSS | MC-SLA-3 | 640-R | MC-SLA-17 | 81L-25-1.... | PC-PPC-3 |
| 6001-SS | MC-SLA-3 | 650 | MC-SLA-18 | 8215 | MC-PSC-28 |
| 6004 | MC-SLA-27 | 650-M | MC-SLA-18 | 821512 | MC-PSC-22, 31 |
| 6004-MM | MC-SLA-27 | 670-1MBPLS | MC-SLA-31 | 821513 | MC-PSC-22, 31 |
| 6004-MMR | MC-SLA-27 | 675-1MBPLS | MC-SLA-31 | 821553 | MC-PSC-31 |
| 6004-R | MC-SLA-27 | 690-1MBPLS | MC-SLA-31 | 821556 | MC-PSC-22, 31 |
| 601 | MC-SLA-4 | 695-1MBPLS | MC-SLA-31 | 8216 | MC-PSC-28 |
| 601-M | MC-SLA-4 | 7-101 | MC-VHD-40 | 827-S | MC-PTC-21 |
| 601-O | MC-SLA-4 | 7/1/58 | MC-VHD-40 | 827-SE | MC-PTC-21 |
| 601-OSS | MC-SLA-4 | 7/1/59 | MC-VHD-40 | 827-U | MC-PTC-21 |
| 601-SS | MC-SLA-4 | 7/1/60 | MC-VHD-40 | 827-UE | MC-PTC-21 |
| 6015 | MC-SLA-5 | 705384 | MC-HYD-5 | 82D40-2... | PC-PPC-67 |
| 6015-M | MC-SLA-5 | 705512 | MC-HYD-5 | 82D63-5... | PC-PPC-67 |
| 6015-MR | MC-SLA-5 | 705634 | MC-HYD-5 | 82L-12-4... | PC-PPC-7 |
| 6015-MSS | MC-SLA-5 | 800 | MC-PTC-29 | 82L-16-4... | PC-PPC-7 |
| 6015-R | MC-SLA-5 | 800-E | MC-PTC-29 | 82L-20-4... | PC-PPC-7 |
| 6015-SS | MC-SLA-5 | 8007-E | MC-PTC-13 | 82L-25-4... | PC-PPC-7 |
| 602 | MC-SLA-25 | 8007-EHL | MC-PTC-13 | 82L2G-2... | PC-PPC-15 |
| 602-MM | MC-SLA-25 | 8007-EHR | MC-PTC-13 | 82L3G-2... | PC-PPC-15 |
| 602-MMSS | MC-SLA-25 | 8015 | MC-PSC-28 | 82L3N-2... | PC-PPC-15 |
| 602-SS | MC-SLA-25 | 801528 | MC-PSC-22, 31 | 82L4G-2... | PC-PPC-15 |
| 602106-M | MC-SLA-28 | 801529 | MC-PSC-22, 31 | 82L4N-2... | PC-PPC-15 |
| 603 | MC-SLA-7 | 801532 | MC-PSC-22, 31 | 82M-3E....40 | PC-PPC-29 |
| 603-M | MC-SLA-7 | 801553 | MC-PSC-31 | 82M-3E...5. | PC-PPC-29 |
| 603-MR | MC-SLA-7 | 8016 | MC-PSC-28 | 82M-3E...6. | PC-PPC-29 |
| 603-MSS | MC-SLA-7 | 802-U | MC-PTC-5 | 82M-3E...8. | PC-PPC-29 |
| 603-R | MC-SLA-7 | 802-UE | MC-PTC-5 | 82M-3E..H040.. | PC-PPC-41 |
| 603-SS | MC-SLA-7 | 8021 | MC-PTC-19 | 82M-3E..H05... | PC-PPC-41 |
| 604 | MC-SLA-25 | 8021-UE | MC-PTC-19 | 82M-3E..H06.. | PC-PPC-41 |
| 604-MM | MC-SLA-25 | 803 | MC-PTC-25 | 82M-3E..H08.. | PC-PPC-41 |
| 604-MMSS | MC-SLA-25 | 803-ME | MC-PTC-25 | 82ZB-004-1 | PC-PPC-4, 8 |
| 604-SS | MC-SLA-25 | 8031 | MC-PTC-26 | 82ZB-036-1 | PC-PPC-22 |
| 604106 | MC-SLA-28 | 807-S | MC-PTC-7 | 82ZB-037-1 | PC-PPC-22 |
| 604106-M | MC-SLA-28 | 807-SE | MC-PTC-7 | 82ZB-038-1 | PC-PPC-22 |
| 605 | MC-SLA-9 | 807-U | MC-PTC-7 | 82ZB-039-1 | PC-PPC-42 |
| 605-M | MC-SLA-9 | 807-UE | MC-PTC-7 | 82ZB-084-1 | PC-PPC-42 |
| 606 | MC-SLA-10 | 8071 | MC-PTC-19 | 82ZB-162-1 | PC-PPC-42 |
| 606-M | MC-SLA-10 | 8071-UE | MC-PTC-19 | 82ZB-SH4001 | PC-PPC-23, 74 |
| 607 | MC-SLA-11 | 810-S | MC-PTC-9 | 82ZB-SH4002 | PC-PPC-23, 74 |
| 607-M | MC-SLA-11 | 810-SE | MC-PTC-9 | 82ZB-SH4005 | PC-PPC-23, 74 |
| 607-SQ | MC-SLA-11 | 810-U | MC-PTC-9 | 82ZB-SH4010 | PC-PPC-23, 74 |
| 607-SQM | MC-SLA-11 | 810-UE | MC-PTC-9 | 82ZB-SH4020 | PC-PPC-23, 74 |
| 608 | MC-SLA-7 | 810151 | MC-PSC-40 | 82ZB-SH4050 | PC-PPC-74 |
| 608-M | MC-SLA-7 | 810153 | MC-PSC-40 | 82ZB-SH5001 | PC-PPC-74 |
| 609 | MC-SLA-12 | 810155 | MC-PSC-40 | 82ZB-SH5002 | PC-PPC-74 |
| 609-B | MC-SLA-12 | 810156 | MC-PSC-40 | 82ZB-SH5005 | PC-PPC-74 |
| 610 | MC-SLA-13 | 810157 | MC-PSC-40 | 82ZB-SH5010 | PC-PPC-74 |

CLAMPING TECHNOLOGY

Product Index

| Model No. | Page | Model No. | Page | Model No. | Page |
|--------------|-----------|---------------|-----------------------|-----------------|-------------------|
| 82ZB-SH5020 | PC-PPC-74 | 89R40-010-2 | MC-PSC-8 | 8JG-169-2-01 | PC-PPC-44 |
| 82ZB-SH5050 | PC-PPC-74 | 89R40-025-2 | MC-PSC-8 | 8JG-17(*)-2-01 | PC-PPC-46 |
| 830 | MC-PTC-27 | 89R50-025-2 | MC-PSC-8 | 8JG-215-1 | MC-PSC-11, 17, 26 |
| 830-ME | MC-PTC-27 | 89R63-025-2 | MC-PSC-8 | 8JG-217-1 | MC-PSC-11, 17, 26 |
| 8315 | MC-PSC-19 | 8AB-151-1 | PC-PPC-42 | 8JG-218-1 | MC-PSC-11, 17, 26 |
| 8316 | MC-PSC-19 | 8AB-152-1 | PC-PPC-42 | 8JG-219-1 | MC-PSC-11, 17, 26 |
| 8415 | MC-PSC-28 | 8AB-153-1 | PC-PPC-42 | 8JG-220-1 | MC-PSC-11, 17, 26 |
| 841550 | MC-PSC-31 | 8AB-154-1 | PC-PPC-42 | 8JG-363-1-01 | PC-PPC-21, 23 |
| 8416 | MC-PSC-28 | 8CE-282-1 | PC-PPC-23 | 8JG-364-1-01 | MC-SLA-21, 23 |
| 846 | MC-PTC-11 | 8CE-284-1 | PC-PPC-23 | 8JG-401-1-01 | PC-PPC-13 |
| 847-S | MC-PTC-15 | 8CE-286-1 | PC-PPC-23 | 8JG-402-1-01 | PC-PPC-13 |
| 847-U | MC-PTC-15 | 8CE-288-1 | PC-PPC-23 | 8JG-403-1-01 | PC-PPC-13 |
| 850 | MC-PTC-28 | 8CE-290-1 | PC-PPC-23 | 8JG-404-1-01 | PC-PPC-13 |
| 850-ME | MC-PTC-28 | 8CE-292-1 | PC-PPC-23 | 8KB-031-1 | MC-SLA-23 |
| 858 | MC-PTC-17 | 8CE-296-1 | PC-PPC-23 | 8KB-032-1 | MC-SLA-23 |
| 858-E | MC-PTC-17 | 8CE-298-1 | PC-PPC-23 | 8MA-061-1 | MC-PSC-13 |
| 860 | MC-PPC-59 | 8CE-300-1 | PC-PPC-23 | 8MA-063-1 | MC-PSC-13 |
| 861 | MC-PPC-59 | 8CE-302-1 | PC-PPC-23 | 8MA-064-1 | MC-PSC-13 |
| 8610100 | MC-PPC-59 | 8CE-304-1 | PC-PPC-23 | 8MA-065-1 | MC-PSC-13 |
| 865132-MR | MC-PPC-59 | 8CE-306-1 | PC-PPC-23 | 8MA-066-1 | MC-PSC-13 |
| 865133-MR | MC-PPC-59 | 8CE-310-1 | PC-PPC-23 | 8MA-084-1 | MC-PSC-11, 17, 26 |
| 868 | MC-PTC-23 | 8CE-312-1 | PC-PPC-23 | 8MA-086-1 | MC-PSC-11, 17, 26 |
| 868-E | MC-PTC-23 | 8CE-314-1 | PC-PPC-23 | 8MA-087-1 | MC-PSC-11, 17, 26 |
| 870-2 | MC-PPC-57 | 8CE-316-1 | PC-PPC-23 | 8MA-088-1 | MC-PSC-11, 17, 26 |
| 871-2 | MC-PPC-57 | 8CE-318-1 | PC-PPC-23 | 8MA-089-1 | MC-PSC-11, 17, 26 |
| 8725 | MC-PSC-37 | 8CE-320-1 | PC-PPC-23 | 8MA-089-1 | MC-PSC-12 |
| 872550 | MC-PSC-39 | 8CE-326-1 | PC-PPC-74 | 8MA-092-1 | MC-PSC-12 |
| 8732 | MC-PSC-37 | 8CE-328-1 | PC-PPC-74 | 8MA-094-1 | MC-PSC-12 |
| 873250 | MC-PSC-39 | 8CE-330-1 | PC-PPC-74 | 8MA-095-1 | MC-PSC-12 |
| 8732G | MC-PSC-37 | 8CE-332-1 | PC-PPC-74 | 8MA-096-1 | MC-PSC-27 |
| 8740 | MC-PSC-37 | 8CE-334-1 | PC-PPC-74 | 8MA-219-1 | MC-PSC-27 |
| 874050 | MC-PSC-39 | 8CE-336-1 | PC-PPC-74 | 8MA-220-1 | MC-PSC-27 |
| 8740G | MC-PSC-37 | 8CE-338-1 | PC-PPC-74 | 8MA-221-1 | MC-PSC-27 |
| 8750 | MC-PSC-37 | 8CE-340-1 | PC-PPC-74 | 8MA-222-1 | MC-PSC-27 |
| 875050 | MC-PSC-39 | 8CE-342-1 | PC-PPC-74 | 8MA-223-1 | MC-PSC-12 |
| 8750G | MC-PSC-37 | 8CE-346-1 | PC-PPC-74 | 8MW-018-1 | MC-PSC-12 |
| 890 | MC-PPC-59 | 8CE-348-1 | PC-PPC-74 | 8MW-020-1 | MC-PSC-12 |
| 891 | MC-PPC-59 | 8CE-350-1 | PC-PPC-74 | 8MW-021-1 | MC-PSC-12 |
| 8910100 | MC-PPC-59 | 8CE-352-1 | PC-PPC-74 | 8MW-022-1 | MC-PSC-12 |
| 895132-MR | MC-PPC-59 | 8CE-354-1 | PC-PPC-74 | 8MW-023-1 | MC-PSC-12 |
| 895133-MR | MC-PPC-59 | 8CE-356-1 | PC-PPC-74 | 8PW-016-1 | PC-PPC-74 |
| 89B20-010-1L | MC-PSC-14 | 8CE-358-1 | PC-PPC-74 | 8PW-016-1-00 | MC-PSC-12 |
| 89B20-010-1R | MC-PSC-14 | 8CE-360-1 | PC-PPC-74 | 8PW-024-1-00 | MC-PSC-12 |
| 89B30-010-1L | MC-PSC-14 | 8CE-362-1 | PC-PPC-74 | 8PW-024-2 | MC-PSC-12 |
| 89B30-010-1R | MC-PSC-14 | 8EA-024-2 | PC-PPC-74 | 8PW-095-1-00 | PC-PPC-23 |
| 89B40-010-1L | MC-PSC-14 | 8EA-109-1 | MC-PSC-40, SLA-3, 7 | 8PW-095-2 | PC-PPC-23 |
| 89B40-010-1R | MC-PSC-14 | 8EA-120-1 | MC-PSC-40 | 8PW-096-1-00 | PC-PPC-23 |
| 89B50-025-1L | MC-PSC-14 | 8EA-137-1 | PC-PPC-23 | 8PW-096-2 | PC-PPC-23 |
| 89B50-025-1R | MC-PSC-14 | 8EA-138-1 | PC-PPC-23 | 8PW-097-1-00 | PC-PPC-23 |
| 89B63-008-1L | MC-PSC-14 | 8EA-139-1 | PC-PPC-23 | 8PW-097-2 | PC-PPC-23 |
| 89B63-008-1R | MC-PSC-14 | 8EL-002-1 | PC-PPC-23, 42, 73 | 8PW-102-2 | PC-PPC-23 |
| 89E20-010-1L | MC-PSC-23 | 8EL-003-1 | PC-PPC-23, 42, 73 | 8PW-103-2 | PC-PPC-23 |
| 89E20-010-1R | MC-PSC-23 | 8EL-007-1 | PC-PPC-23 | 8S401-15-117 | PC-PPC-47 |
| 89E30-010-1L | MC-PSC-23 | 8EL-009-1 | PC-PPC-23 | 8S501-25-144 | PC-PPC-47, 59 |
| 89E30-010-1R | MC-PSC-23 | 8JG-065-2-01 | PC-PPC-20, 23, 71, 74 | 8S631-25-144 | PC-PPC-48, 59 |
| 89E40-010-1L | MC-PSC-23 | 8JG-066-1-01 | PC-PPC-20, 23, 71, 74 | 8S631-45-144 | PC-PPC-48, 59 |
| 89E40-010-1R | MC-PSC-23 | 8JG-067-2-01 | PC-PPC-20, 23 | 8S631-75-204 | PC-PPC-48, 59 |
| 89E50-025-1L | MC-PSC-23 | 8JG-068-1-01 | PC-PPC-20, 23 | 8S801-45-204 | PC-PPC-48 |
| 89E50-025-1R | MC-PSC-23 | 8JG-069-1-01 | PC-PPC-70,74 | 8U(*)405-00-117 | PC-PPC-45 |
| 89E63-008-1L | MC-PSC-23 | 8JG-070-1-01 | PC-PPC-47, 59, 72, 74 | 8U(*)405-15-117 | PC-PPC-45 |
| 89E63-008-1R | MC-PSC-23 | 8JG-075-3-01 | PC-PPC-20, 23 | 8U(*)405-25-117 | PC-PPC-45 |
| 89R20-010-2 | MC-PSC-8 | 8JG-080-1-01 | PC-PPC-48, 59 | 8U(*)405-45-107 | PC-PPC-45 |
| 89R32-010-2 | MC-PSC-8 | 8JG-1179-1-01 | PC-PPC-48 | 8U(*)501-25-144 | PC-PPC-47, 59 |

CLAMPING TECHNOLOGY

Product Index

| Model No. | Page | Model No. | Page | Model No. | Page |
|-----------------|---------------|-------------|---------------|----------------|---------------|
| 8U(*)504-15-144 | PC-PPC-45, 59 | B8JG-1011-1 | PC-PPC-51, 62 | B8JG-1227-1 | PC-PPC-49, 60 |
| 8U(*)504-25-144 | PC-PPC-45, 59 | B8JG-1012-1 | PC-PPC-51, 62 | B8JG-1228-1 | PC-PPC-49, 60 |
| 8U(*)504-45-144 | PC-PPC-45, 59 | B8JG-1019-1 | PC-PPC-51, 62 | B8JG-1507-1 | PC-PPC-50, 61 |
| 8U(*)631-15-144 | PC-PPC-46, 58 | B8JG-1020-1 | PC-PPC-51, 62 | B8JG-1508-1 | PC-PPC-50, 61 |
| 8U(*)631-25-144 | PC-PPC-46, 58 | B8JG-1021-1 | PC-PPC-51, 62 | B8JG-1509-1 | PC-PPC-50, 61 |
| 8U(*)631-45-144 | PC-PPC-46, 58 | B8JG-1022-1 | PC-PPC-51, 62 | B8JG-1510-1 | PC-PPC-50, 61 |
| 8U(*)631-75-204 | PC-PPC-46, 58 | B8JG-1023-1 | PC-PPC-51, 62 | B8JG-1511-1 | PC-PPC-50, 61 |
| 8UM405-00-117 | PC-PPC-43 | B8JG-1024-1 | PC-PPC-51, 62 | B8JG-1512-1 | PC-PPC-50, 61 |
| 8UM405-15-117 | PC-PPC-43 | B8JG-1031-1 | PC-PPC-51, 62 | B8JG-1519-1 | PC-PPC-50, 61 |
| 8UM405-25-117 | PC-PPC-43 | B8JG-1032-1 | PC-PPC-51, 62 | B8JG-1520-1 | PC-PPC-50, 61 |
| 8UM405-45-107 | PC-PPC-43 | B8JG-1033-1 | PC-PPC-51, 62 | B8JG-1521-1 | PC-PPC-50, 61 |
| 8UM501-15-144 | PC-PPC-43, 57 | B8JG-1034-1 | PC-PPC-51, 62 | B8JG-1522-1 | PC-PPC-50, 61 |
| 8UM501-25-144 | PC-PPC-43, 57 | B8JG-1035-1 | PC-PPC-51, 62 | B8JG-1523-1 | PC-PPC-50, 61 |
| 8UM501-45-144 | PC-PPC-43, 57 | B8JG-1036-1 | PC-PPC-51, 62 | B8JG-1524-1 | PC-PPC-50, 61 |
| 8UM631-15-144 | PC-PPC-44, 58 | B8JG-1043-1 | PC-PPC-51, 62 | B8JG-1531-1 | PC-PPC-50, 61 |
| 8UM631-25-144 | PC-PPC-44, 58 | B8JG-1044-1 | PC-PPC-51, 62 | B8JG-1532-1 | PC-PPC-50, 61 |
| 8UM631-45-144 | PC-PPC-44, 58 | B8JG-1045-1 | PC-PPC-51, 62 | B8JG-1533-1 | PC-PPC-50, 61 |
| 8UM631-75-204 | PC-PPC-44, 58 | B8JG-1046-1 | PC-PPC-51, 62 | B8JG-1534-1 | PC-PPC-50, 61 |
| 8UM801-45-204 | PC-PPC-44 | B8JG-1047-1 | PC-PPC-51, 62 | B8JG-1535-1 | PC-PPC-50, 61 |
| 905 | MC-ACC-3 | B8JG-1048-1 | PC-PPC-51, 62 | B8JG-1536-1 | PC-PPC-50, 61 |
| 905-M | MC-ACC-3 | B8JG-1110-1 | PC-PPC-52 | B8JG-1543-1 | PC-PPC-50, 61 |
| 91090 | MC-VHD-36 | B8JG-1111-1 | PC-PPC-52 | B8JG-1544-1 | PC-PPC-50, 61 |
| 920 | MC-ACC-3 | B8JG-1112-1 | PC-PPC-52 | B8JG-1545-1 | PC-PPC-50, 61 |
| 920-M | MC-ACC-3 | B8JG-1113-1 | PC-PPC-52 | B8JG-1546-1 | PC-PPC-50, 61 |
| 95030 | MC-SLA-19 | B8JG-1114-1 | PC-PPC-52 | B8JG-1547-1 | PC-PPC-50, 61 |
| 95040 | MC-SLA-19 | B8JG-1115-1 | PC-PPC-52 | B8JG-1548-1 | PC-PPC-50, 61 |
| 95050 | MC-SLA-19 | B8JG-1116-1 | PC-PPC-52 | B8JG-3236-1 | PC-PPC-49, 60 |
| 95060 | MC-SLA-19 | B8JG-1117-1 | PC-PPC-52 | B8JG-3237-1 | PC-PPC-49, 60 |
| 9522-2L | MC-PSC-3 | B8JG-1118-1 | PC-PPC-52 | B8JG-3238-1 | PC-PPC-49, 60 |
| 9522-2R | MC-PSC-3 | B8JG-1130-1 | PC-PPC-52 | B8JG-3246-1 | PC-PPC-49, 60 |
| 9522150 | MC-PSC-7 | B8JG-1131-1 | PC-PPC-52 | B8JG-3247-1 | PC-PPC-49, 60 |
| 9522153 | MC-PSC-7 | B8JG-1132-1 | PC-PPC-52 | B8JG-3248-1 | PC-PPC-49, 60 |
| 952260 | MC-PSC-6 | B8JG-1133-1 | PC-PPC-52 | B8JG-3256-1 | PC-PPC-49, 60 |
| 952261 | MC-PSC-6 | B8JG-1134-1 | PC-PPC-52 | B8JG-3257-1 | PC-PPC-49, 60 |
| 952262 | MC-PSC-6 | B8JG-1135-1 | PC-PPC-52 | B8JG-3258-1 | PC-PPC-49, 60 |
| 9530-2GL | MC-PSC-3 | B8JG-1136-1 | PC-PPC-52 | BIM-IKE-AP | MC-SLA-47 |
| 9530-2GR | MC-PSC-3 | B8JG-1137-1 | PC-PPC-52 | BK-R25-82L25-1 | PC-PPC-21 |
| 9530-2L | MC-PSC-3 | B8JG-1138-1 | PC-PPC-52 | BK-R25-82L32-1 | PC-PPC-21 |
| 9530-2R | MC-PSC-3 | B8JG-1150-1 | PC-PPC-52 | BK-R25-82L40-1 | PC-PPC-21 |
| 953060 | MC-PSC-6 | B8JG-1151-1 | PC-PPC-52 | CABL-010 | MC-PSC-41 |
| 953061 | MC-PSC-6 | B8JG-1152-1 | PC-PPC-52 | CABL-013 | MC-PSC-41 |
| 953062 | MC-PSC-6 | B8JG-1153-1 | PC-PPC-52 | F-160 | MC-VSC-3 |
| 9540-2GL | MC-PSC-3 | B8JG-1154-1 | PC-PPC-52 | FL-120/-- | MC-VSC-3 |
| 9540-2GR | MC-PSC-3 | B8JG-1155-1 | PC-PPC-52 | FL-121/45 | MC-VSC-3 |
| 9540-2L | MC-PSC-3 | B8JG-1156-1 | PC-PPC-52 | FL-122/45 | MC-VSC-3 |
| 9540-2R | MC-PSC-3 | B8JG-1157-1 | PC-PPC-52 | FL-160/-- | MC-VSC-3 |
| 9540150 | MC-PSC-7 | B8JG-1158-1 | PC-PPC-52 | FL-161/60 | MC-VSC-3 |
| 9540153 | MC-PSC-7 | B8JG-1170-1 | PC-PPC-52 | FL-162/60 | MC-VSC-3 |
| 954060 | MC-PSC-6 | B8JG-1171-1 | PC-PPC-52 | FO-082/40 | MC-VSC-3 |
| 954061 | MC-PSC-6 | B8JG-1172-1 | PC-PPC-52 | FO-120/-- | MC-VSC-3 |
| 9550-2GL | MC-PSC-3 | B8JG-1173-1 | PC-PPC-52 | FO-121/45 | MC-VSC-3 |
| 9550-2GR | MC-PSC-3 | B8JG-1174-1 | PC-PPC-52 | FO-122/45 | MC-VSC-3 |
| 9550-2L | MC-PSC-3 | B8JG-1175-1 | PC-PPC-52 | FO-160/-- | MC-VSC-3 |
| 9550-2R | MC-PSC-3 | B8JG-1176-1 | PC-PPC-52 | FO-161/60 | MC-VSC-3 |
| 9550150 | MC-PSC-7 | B8JG-1177-1 | PC-PPC-52 | FO-162/60 | MC-VSC-3 |
| 9550153 | MC-PSC-7 | B8JG-1178-1 | PC-PPC-52 | FO-220/-- | MC-VSC-3 |
| 955060 | MC-PSC-6 | B8JG-1206-1 | PC-PPC-49, 60 | FO-221/80 | MC-VSC-3 |
| 955061 | MC-PSC-6 | B8JG-1207-1 | PC-PPC-49, 60 | G-082/40 | MC-VSC-3 |
| 955062 | MC-PSC-6 | B8JG-1208-1 | PC-PPC-49, 60 | G-120/-- | MC-VSC-3 |
| B8JG-1007-1 | PC-PPC-51, 62 | B8JG-1216-1 | PC-PPC-49, 60 | G-121-45 | MC-VSC-3 |
| B8JG-1008-1 | PC-PPC-51, 62 | B8JG-1217-1 | PC-PPC-49, 60 | G-122-45 | MC-VSC-3 |
| B8JG-1009-1 | PC-PPC-51, 62 | B8JG-1218-1 | PC-PPC-49, 60 | K XXXX-...-A | MC-PPC-10 |
| B8JG-1010-1 | PC-PPC-51, 62 | B8JG-1226-1 | PC-PPC-49, 60 | K XXXX-...-K | MC-PPC-11 |

CLAMPING TECHNOLOGY

Product Index

| Model No. | Page | Model No. | Page |
|----------------|-----------|----------------|----------|
| K-1222 | MC-VSC-7 | WK1000-200-7-1 | MC-PPC-6 |
| K-508 | MC-VSC-7 | WK1000-30-7-1 | MC-PPC-6 |
| K-612 | MC-VSC-7 | WK1000-50-7-1 | MC-PPC-6 |
| K-816 | MC-VSC-7 | WK1000-70-7-1 | MC-PPC-6 |
| K1000-120-7-1 | MC-PPC-3 | WK3000-120-6-1 | MC-PPC-6 |
| K1000-15-7-1 | MC-PPC-3 | WK3000-15-6-1 | MC-PPC-6 |
| K1000-200-7-1 | MC-PPC-3 | WK3000-200-6-1 | MC-PPC-6 |
| K1000-30-7-1 | MC-PPC-3 | WK3000-30-6-1 | MC-PPC-6 |
| K1000-50-7-1 | MC-PPC-3 | WK3000-50-6-1 | MC-PPC-6 |
| K1000-70-7-1 | MC-PPC-3 | WK3000-70-6-1 | MC-PPC-6 |
| K3000-120-6-1 | MC-PPC-3 | WK400-120-6-1 | MC-PPC-6 |
| K3000-15-6-1 | MC-PPC-3 | WK400-15-6-1 | MC-PPC-6 |
| K3000-200-6-1 | MC-PPC-3 | WK400-200-6-1 | MC-PPC-6 |
| K3000-30-6-1 | MC-PPC-3 | WK400-30-6-1 | MC-PPC-6 |
| K3000-50-6-1 | MC-PPC-3 | WK400-50-6-1 | MC-PPC-6 |
| K3000-70-6-1 | MC-PPC-3 | WK400-70-6-1 | MC-PPC-6 |
| K400-120-6-1 | MC-PPC-3 | WK4500-120-6-1 | MC-PPC-6 |
| K400-15-6-1 | MC-PPC-3 | WK4500-15-6-1 | MC-PPC-6 |
| K400-200-6-1 | MC-PPC-3 | WK4500-200-6-1 | MC-PPC-6 |
| K400-30-6-1 | MC-PPC-3 | WK4500-30-6-1 | MC-PPC-6 |
| K400-50-6-1 | MC-PPC-3 | WK4500-50-6-1 | MC-PPC-6 |
| K400-70-6-1 | MC-PPC-3 | WK4500-70-6-1 | MC-PPC-6 |
| K4500-120-6-1 | MC-PPC-3 | WK600-120-6-1 | MC-PPC-6 |
| K4500-15-6-1 | MC-PPC-3 | WK600-15-6-1 | MC-PPC-6 |
| K4500-200-6-1 | MC-PPC-3 | WK600-200-6-1 | MC-PPC-6 |
| K4500-30-6-1 | MC-PPC-3 | WK600-30-6-1 | MC-PPC-6 |
| K4500-50-6-1 | MC-PPC-3 | WK600-50-6-1 | MC-PPC-6 |
| K4500-70-6-1 | MC-PPC-3 | WK600-70-6-1 | MC-PPC-6 |
| K600-120-6-1 | MC-PPC-3 | WK6000-120-6 | MC-PPC-6 |
| K600-15-6-1 | MC-PPC-3 | WK6000-30-6 | MC-PPC-6 |
| K600-200-6-1 | MC-PPC-3 | WK6000-50-6 | MC-PPC-6 |
| K600-30-6-1 | MC-PPC-3 | WK6000-70-6 | MC-PPC-6 |
| K600-50-6-1 | MC-PPC-3 | WR 2000-120-7 | MC-PPC-9 |
| K600-70-6-1 | MC-PPC-3 | WR 2000-15-7 | MC-PPC-9 |
| L-213-1-01 | MC-ACC-8 | WR 2000-30-7 | MC-PPC-9 |
| L-213-1-02 | MC-ACC-8 | WR 2000-50-7 | MC-PPC-9 |
| L-213-2-01 | MC-ACC-8 | WR 2000-70-7 | MC-PPC-9 |
| L-213-2-02 | MC-ACC-8 | | |
| L-213-3-01 | MC-ACC-9 | | |
| L-213-4-01 | MC-ACC-10 | | |
| L-217-1-01 | MC-ACC-8 | | |
| L-217-1-02 | MC-ACC-8 | | |
| L-217-1-03 | MC-ACC-8 | | |
| L-217-2-01 | MC-ACC-8 | | |
| L-217-2-02 | MC-ACC-8 | | |
| L-217-3-01 | MC-ACC-9 | | |
| L-217-4-01 | MC-ACC-10 | | |
| L-227-1-01 | MC-ACC-8 | | |
| L-227-1-02 | MC-ACC-8 | | |
| L-227-1-03 | MC-ACC-8 | | |
| L-227-1-04 | MC-ACC-8 | | |
| L-227-2-01 | MC-ACC-8 | | |
| L-227-2-02 | MC-ACC-8 | | |
| L-227-3-01 | MC-ACC-9 | | |
| L-227-4-01 | MC-ACC-10 | | |
| SMB-102157 | MC-PPC-10 | | |
| TCC-2.....4. | PC-PPC-25 | | |
| TCC-2E.....5. | PC-PPC-25 | | |
| TCC-2.....6. | PC-PPC-25 | | |
| WK XXXX-...-A | MC-PPC-10 | | |
| WK XXXX-...-K | MC-PPC-11 | | |
| WK1000-120-7-1 | MC-PPC-5 | | |
| WK1000-15-7-1 | MC-PPC-6 | | |

OUR PORTFOLIO OF PRODUCTS



End Effectors (EE)

- Tool Changers
- End-of-Arm Tooling
- Vacuum Products
- Palletizing Solutions




Grippers (GR)

- Electric Grippers
- Pneumatic and Sheet Metal Grippers
- Rotates
- Slides



Indexers (IN)

- Precision Conveyors
- Dial Indexers
- Shaft and Flange Indexers
- Part Handlers




Power Clamps (PC)

- Power Clamps
- Pin Clamps and Packages
- Pivot Units
- Power Cylinders




Manual Clamps (MC)

- Hold Down
- Squeeze Action
- Plunger, Hook and Latch
- Pneumatic Toggle and Swing



Remote Handling (RH)

- Gloveport Systems
- Transfer Systems
- Telemanipulators
- Waste Drum Systems



GLOBAL LOCATIONS

NORTH AMERICA

Corporate Headquarters

Auburn Hills, Michigan
Toll Free: 1.888.DESTACO
Marketing: marketing@destaco.com

Global Technology Center

Auburn Hills, Michigan
Tel: 1.248.836.6700
Customer Service: customerservice@destaco.com

Mt. Juliet, Tennessee
Tel: 1.888.DESTACO
Customer Service: customerservice@destaco.com

Wheeling, Illinois
Tel: 1.800.645.5207
Customer Service: camco@destaco.com

Red Wing, Minnesota (Central Research Laboratories)
Tel: 651.385.2142
Customer Service: sales@centres.com

ASIA

Bangkok, Thailand
Tel: +66-2-326-0812
Customer Service: info@destaco.com

Shanghai, China
Tel: +86-21-6081-2888
Customer Service: china@destaco.com

Bangalore, India
Tel: +91-80-41123421-426
Customer Service: india@destaco.com

EUROPE

Oberursel, Germany
Tel: +49-6171-705-0
Customer Service: europe@destaco.com

Sainte Florine, France
Tel: +33-4-73545001
Customer Service: france@destaco.com

Wolverhampton, United Kingdom
Tel: +44-1902-797980
Customer Service: uk@destaco.com

Sant Boi de Llobregat, Spain
Tel: +34-936361680
Customer Service: spain@destaco.com

Uithoorn, Netherlands
Tel: +31-297285332
Customer Service: benelux@destaco.com