13


Steam traps

Swivel connectors and traps

TI-P128-17 CMGT Issue 3



IPC20 and IPC21 **Pipeline Connectors with Integral Spiratec Sensors**



Description

The IPC20 is a pipeline connector with integral strainer and Spiratec sensor for use with UTD52L, UTD52H, UTD30L, UTD30H, UBP21 and UBP32 steam traps.

The IPC21 is a pipeline connector with an integral strainer and Spiratec sensor for use with UIB30, UIB30H, UFT14 and UFT32 steam

Both the IPC20 and IPC21 can be fitted with the following sensor options:

SS1 sensor - for detection of steam leakage.

WLS1 sensor with diode - for use with R16C monitor to detect steam wastage and waterlogging.

WLS1 sensor without diode - for use with R1C to detect steam wastage and waterlogging.

Standards

These products fully comply with the requirements of the Pressure Equipment Directive (PED).

Certification

These products are available with certification to EN 10204 2.2.

Note: All certification/inspection requirements must be stated at the time of order placement.


Sizes and pipe connections

Condensate inlet/outlet DN15, 20 and 25 Screwed BSP, NPT Socket weld ends to ANSI B 16.11/BS 3799 Class 3000.

First for Steam Solutions

Steam traps


Swivel connectors and traps



No.Part		Material	Material		
1	Body	Austenitic stainless steel	ASTM A 351 CF8		
2	Strainer screen	Austenitic stainless steel (0.8 mm perforations)	316L		
3	Strainer cap	Austenitic stainless steel	AISI 303		
4	Cap gasket	Stainless steel	BS 1449 304 S16		
8	Sensor	Stainless steel	ASTM A582 416		
9	Sensor gasket	Stainless steel			

14

Pressure/temperature limits





*PMO Maximum operating pressure recommended for saturated steam service

Body	design conditions	ANSI/ASME Class 300 (PN50)
РМА	Maximum allowable pressure	50 bar g
TMA	Maximum allowable temperature	240 °C
РМО	Maximum operating pressure for saturated steam service	32 bar g
ТМО	Maximum operating temperature	240 °C
Desig	76 bar g	

15


Page 3 of 4


Steam traps

Swivel connectors and traps

Dimensions/weights (approximate) in mm and kg

Size	Α	В	С	D	Weight
1/2"	81	24	127	58	1.20
3/4"	89	24	127	64	1.30
1"	99	25	132	69	1.50





K, values

Size	DN15	DN20	DN25	
K _v	1.1	1.1	1.1	

For conversion: $C_v (UK) = K_v \times 0.963$ $C_v (US) = K_v \times 1.156$

Safety information, installation and maintenance

For full details see the Installation and Maintenance Instructions (IM-P128-11) supplied with the product.

General information

There are two criteria which must be satisfied to ensure that the swivel connector trap will operate correctly and ensure effective condensate removal:

- The IPC20 and IPC21 must be installed in a horizontal pipeline with the sensor at the bottom.
- The connection face for the swivel connector steam trap must always be in the vertical plane unless stated on relevant steam trap Installation and Maintenance Instructions.

After installation it is recommended that the pipeline connector is insulated to minimise radiated heat losses and to protect personnel

Detailed instructions regarding welding socket weld versions are provided with the product.

Disposal

This product is recyclable. No ecological hazard is anticipated with disposal of this product providing due care is taken.

How to order

Example: 1 off 1/2" Spirax Sarco IPC21 pipeline connector with socket weld connections fitted with an integral strainer screen and SS1 Spiratec sensor for steam wastage detection.

Steam traps

Swivel connectors and traps


The spare parts available are detailed below. No other parts are supplied as spares.

Available spares

Strainer screen and gasket	2, 4
Sensor and sensor gasket	8, 9

How to order spares

Always order spares using the description given in the column headed 'Available spares' and state the size and model number. **Example:** 1 - Strainer screen and gasket for the ½" IPC20 connector.



Recommended tightening torques

Item		or mm	N m
3	32 A/F	M28 x 1.5P	170 - 190
8	24 A/F		50 - 55