


List of Motor parts

Frame Size: 56÷90



Item	Description
1	stator
2	rotor
3	key
4	bearing
5	DE shield
6	flange B5
7	flange B14/C1
8	flange B14/C2
9	NDE shield
10	foot
11	shaft seal (IP55)
12	spring washer
13	tie rod
14	fan
15	fan cover
16	name plate
17	terminal box gasket
18	terminal box
19	cable gland
20	O-ring (IP55)
21	terminal board
22	terminal box cap gasket
23	terminal box cap
24	seal
25	mounting plate of capacitor
26	capacitor
27	nut M8

DE – drive end
NDE – non drive end

Ordering information

In order to select the proper motor and provide you the most accurate offer as the requirements of customer's applications are various, we ask you to specify below motor details:

Orders for motors should specify

- » motor type designation,
- » rated output,
- » rated speed,
- » operating duty,
- » supply voltage and connection,
- » frequency,
- » mounting arrangements, end shield material,
- » degree of protection,
- » type of driven machine,
- » other details regarding special requests,

and information concerning additional accessories e.g.

- » thermal protection,
- » anticondensation heaters,
- » vibration sensors,
- » etc.

When ordering special purpose motors one should also indicate:

- » required direction of rotation,
- » required degree of interior protection,
- » method of start-up,
- » method of coupling with the driven unit (gears, dimensions of belt pulleys, etc.),
- » type of driven machine (type of load), including the moment of inertia J or flywheel effect GD2 calculated to motor shaft,
- » other customer's specifications.

When ordering spare parts one should specify:

- » full designation of the motor type including its serial number (provided on the nameplate) or catalogue number,
- » degree of protection,
- » mounting arrangement,
- » name of part,
- » number of pieces.

As part of our development program, we reserve the right to alter or amend any of the specifications without giving prior notice.