



CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION  
HIGH AND EXTREMELY HIGH CRIMPING FITTINGS  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**

**SISTEMA BSPP / BSPP O'RIN SYSTEM / SYSTEM BSPP O-RING**



**HEMBRA GIRATORIA BSPP O-RING / BSPP O'RING SWIVEL  
FEMALE / FEMELLE TOURNANTE BSPP O-RING**



Ref.		
RACA30111212	3/4	3/4
RACA30111612	1"	3/4
RACA30111616	1"	1"
RACA30112016	1" 1/4	1"
RACA30112020	1" 1/4	1" 1/4
RACA30112420	1" 1/2	1" 1/4
RACA30112424	1" 1/2	1" 1/2
RACA30113224	2"	1" 1/2
RACA30113232	2"	2"



**HEMBRA GIRATORIA 45° BSPP O-RING / 45° BSPP O-RING  
SWIVEL FEMALE / FEMELLE TOURNANTE 45° BSPP O-RING**



Ref.		
RACA30161212	3/4	3/4
RACA30161612	1"	3/4
RACA30161616	1"	1"
RACA30162016	1" 1/4	1"
RACA30162020	1" 1/4	1" 1/4
RACA30162420	1" 1/2	1" 1/4
RACA30162424	1" 1/2	1" 1/2
RACA30163232	2"	2"



**MACHO FIJO BSPP / BSPP STUD MALE / MÂLE FIXE BSPP**



Ref.		
RACA30131212	3/4	3/4
RACA30131612	1"	3/4
RACA30131616	1"	1"
RACA30132016	1" 1/4	1"
RACA30132020	1" 1/4	1" 1/4
RACA30132420	1" 1/2	1" 1/4
RACA30132424	1" 1/2	1" 1/2
RACA30133232	2"	2"



**MACHO FIJO NPTF / NPTF STUD MALE / MÂLE FIXE NPTF**



Ref.		
RACA30231212	3/4	3/4
RACA30231616	1"	1"
RACA30232020	1" 1/4	1" 1/4
RACA30232424	1" 1/2	1" 1/2
RACA30233232	2"	2"



**HEMBRA GIRATORIA 90° BSPP O'RING / 90° BSPP SWIVEL  
FEMALE O'RING / FEMELLE TOURNANTE 90° BSPP O-RING**



Ref.		
RACA30151212	3/4	3/4
RACA30151612	1"	3/4
RACA30151616	1"	1"
RACA30152016	1" 1/4	1"
RACA30152020	1" 1/4	1" 1/4
RACA30152420	1" 1/2	1" 1/4
RACA30152424	1" 1/2	1" 1/2
RACA30153224	2"	1" 1/2
RACA30153232	2"	2"

**MACHO FIJO BSPT / BSPT STUD MALE /  
MÂLE FIXE BSPT**



Ref.		
RACA30331212	3/4	3/4
RACA30331616	1"	1"
RACA30332020	1" 1/4	1" 1/4
RACA30332424	1" 1/2	1" 1/2
RACA30333232	2"	2"

CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION  
HIGH AND EXTREMELY HIGH CRIMPING FITTINGS  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**

**RACORD VIN-BLAST / VIN-BLAST FITTING / RACCORD VIN-BLAST**



**CASQUILLO VIN-BLAST /  
VIN-BLAST FERRULE /  
JUPE VIN-BLAST**



Ref.	
RAPBLAS000008	1/2
RAPBLAS000012	3/4



**HEMBRA GIRATORIA MÉTRICA SERIE PESADA VIN-BLAST  
1100 BAR / VIN-BLAST 1100 BARS METRIC SWIVEL FEMALE  
HEAVY SERIES / FEMELLE TOURNANTE MÉTRIQUE SÉRIE  
LOURDE VIN-BLAST 1100 BARS**



Ref.	$\varnothing$		
RAPBLAS912408	16	24x150	1/2
RAPBLAS913012	20	30x200	3/4
RAPBLAS913612	25	36x200	3/4

**HEMBRA GIRATORIA BSPP O-RING VIN-BLAST / VIN-BLAST  
BSPP O-RING SWIVEL FEMALE / FEMELLE TOURNANTE  
BSPP O-RING VIN-BLAST**



Ref.		
RAPBLAS110808	1/2	1/2
RAPBLAS111212	3/4	3/4

**MANGUERA Y CONEXIONES DE CONTROL / HOSE AND CONTROL FITTINGS / TUYAU ET CONNEXIONS DE CONTRÔLE**


**MANGUERA TS8 /  
HOSE TS8 /  
TUYAU TS8**



Ref.			
MSL00702E	630	1890	1/12


**HEMBRA GIRATORIA BSPP PARA MANÓMETRO / BSPP  
SWIVEL FEMALE FOR PRESSURE GAUGE PLUG-IN  
CONNECT. / FEMELLE TOURNANTE BSPP MANOMÈTRE**



Ref.	
RACMH120004	1/4 BSPP
RACMH120008	1/2 BSPP


**HEMBRA GIRATORIA BSPP 60° /  
60° BSPP SWIVEL FEMALE /  
FEMELLE TOURNANTE BSPP 60°**



Ref.	
RACMH110002	1/8 BSPP
RACMH110004	1/4 BSPP

**HEMBRA GIRATORIA TOMA PRESIÓN / SWIVEL FEMALE  
PRESSURE CONNECTION / FEMELLE TOURNANTE PRISSE  
PRESSION**



Ref.	
RACMH131615	16x150
RACMH131620	16x200

CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION  
HIGH AND EXTREMELY HIGH CRIMPING FITTINGS  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**

**TOMA BAYONETA / PLUG-IN CONNECTION /  
PRESSURE CONNECTION**



Ref.

RACMH140000

**ADAPTADOR MANÓMETRO TOMA PASATABIQUES /  
PRESSURE GAUGE ADAPTER BULKHEAD CONNECTION /  
ADAPTEUR MANOMÈTRE PRISSE PASSE-CLOISON**



Ref.



RACMH171604

16x200

1/4

RACMH171608

16x200

1/2

**HEMBRA GIRATORIA CONO 24° / 24° CONE SWIVEL FEMALE  
/ FEMELLE TOURNANTE CÔNE 24°**



Ref.



RACMH150012

12x150

RACMH150014

14x150

**ADAPTADOR MANOMETRO TOMA PRESION HEMBRA  
/ PRESSURE GAUGE ADAPTER FEMALE PRESSURE  
CONNECTION / ADAPTEUR MANOMETRE PRISSE PRESSION  
FEMELLE**



Ref.



RACMH181604

16x200

1/4

RACMH181608

16x200

1/2

**ESPIGA LISA RECTA / STRAIGHT STANDPIPE /  
EMBOUT LISSE DROIT**



Ref.



RACMH160006

6

RACMH160008

8

**ADAPTADOR MANOMETRO TOMA PRESION 90° /  
90° PRESSURE GAUGE CONNECTION ADAPTER /  
ADAPTEUR MANOMÈTRE PRISSE PRESSION 90°**



Ref.



RACMH251604

16x200

1/4

RACMH251608

16x200

1/2

**MACHO FIJO / STUD MALE / MÂLE FIXE**



Ref.



RACMH680002

1/8 BSPP

RACMH880002

1/8 NPTF

**ADAPTADOR TOMA PRESIÓN HEMBRA GIRATORIA MÉTRICA  
/ METRIC SWIVEL FEMALE PRESSURE CONNECTION  
ADAPTER / ADAPTEUR PRISSE PRESSION FEMELLE  
TOURNANTE MÉTRIQUE**



Ref.



RACMH280014

8

14X150

16X200

RACMH220019

10

16X150

16X200

RACMH220018

12

18X150

16X200

RACMH280022

15

22X150

16X200

RACMH220020

22

30X200

16X200

RACMH220021

12

20X150

16X200

RACMH220022

16

24X150

16X200

RACMH220023

20

30X200

16X200

**HEMBRA GIRATORIA SAE / SAE SWIVEL FEMALE /  
FEMELLE TOURNANTE SAE**



Ref.



RACMH770004

7/16

**ESPIGA LISA 90° / 90° STANDPIPE / EMBOUT LISSE 90°**



Ref.



RACMH440006



6

CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION  
HIGH AND EXTREMELY HIGH CRIMPING FITTINGS  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**



**ADAPTADOR TOMA PRESIÓN MACHO BSPP / BSPP MALE  
PRESSURE CONNECTION ADAPTER / ADAPTEUR PRISSE  
PRESSION MÂLE BSPP**



Ref.		
RACMH231602	1/8	16X200
RACMH231604	1/4	16X200
RACMH191606	3/8	16X200
RACMH191608	1/2	16X200



**ADAPTADOR TOMA PRESIÓN MACHO MÉTRICO / METRIC  
MALE PRESSURE CONNECTION ADAPTER / ADAPTEUR  
PRISSE PRESSION MÂLE MÉTRIQUE**



Ref.		
RACMH231608	8x100	16X200
RACMH231610	10x100	16X200
RACMH231612	12x150	16X200
RACMH231614	14x150	16X200
RACMH231616	16x150	16X200



**ADAPTADOR TOMA PRESIÓN MACHO BSPT / BSPT MALE  
PRESSURE CONNECTION ADAPTER / ADAPTEUR PRISSE  
PRESSION MÂLE BSPT**



Ref.		
RACMH201602	1/8	16X200
RACMH201604	1/4	16X200
RACMH201606	3/8	16X200



**ADAPTADOR TOMA PRESIÓN MACHO UNF / UNF MALE  
PRESSURE CONNECTION ADAPTER / ADAPTEUR PRISSE  
PRESSION MÂLE UNF**



Ref.		
RACMH221604	7/16	16X200
RACMH221605	1/2	16X200
RACMH221606	9/16	16X200
RACMH221608	3/4	16X200


**ADAPTADOR TOMA PRESIÓN MACHO NPTF / PTF MALE  
PRESSURE CONNECTION ADAPTER / ADAPTEUR PRISSE  
PRESSION MÂLE NPTF**



Ref.		
RACMH211602	1/8	16X200
RACMH211604	1/4	16X200
RACMH211606	3/8	16X200

**ADAPTADOR TOMA PRESIÓN BAYONETA / PLUG-IN  
PRESSURE CONNECTION ADAPTER / ADAPTEUR PRISSE  
PRESSION BAIONNETTE**



Ref.	
RACMH240100	10x100
RACMH240800	8x100
RACMH240002	1/8
RACMH240004	1/4
RACMH240006	3/8
RACMH240008	1/2



CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION  
HIGH AND EXTREMELY HIGH CRIMPING FITTINGS  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**

**SISTEMA GAZ / GAZ METRIC SYSTEM / METRIQUE GAZ**



**HEMBRA GIRATORIA MÉTRICA GAZ / GAZ METRIC SWIVEL  
FEMALE / FEMELLE TOURNANTE MÉTRIQUE GAZ**



Ref.	∅		
RACG11012005	13	20x150	5/16
RACG11012006	13	20x150	3/8
RACG11012408	17	24x150	1/2
RACG11013010	21	30x150	5/8
RACG11013612	21	36x150	3/4
RACG11014516	33	45x150	1"



**HEMBRA GIRATORIA 90° MÉTRICA GAZ / 90° GAZ METRIC  
SWIVEL FEMALE / FEMELLE TOURNANTE 90° MÉTRIQUE GAZ**



Ref.	∅		
RACG11052006	13	20x150	3/8
RACG11052408	17	24x150	1/2
RACG11053010	21	30x150	5/8
RACG11053612	27	36x150	3/4
RACG11054516	33	45x150	1"

**MACHO FIJO GAZ / GAZ STUD MALE / MÂLE FIXE GAZ**





Ref.	∅		
RACG11032005	13	20x150	5/16
RACG11032006	13	20x150	3/8
RACG11032408	17	24x150	1/2
RACG11033010	21	30x150	5/8
RACG11033612	27	36x150	3/4
RACG11034516	33	45x150	1"

**SISTEMA ORFS / ORFS SYSTEM / ORFS SYSTEM**



**HEMBRA GIRATORIA ORFS / ORFS SWIVEL FEMALE /  
FEMELLE TOURNANTE ORFS**



Ref.		
RACG11110404	9/16	1/4
RACG11110606	11/16	3/8
RACG11110806	13/16	3/8
RACG11110808	13/16	1/2
RACG11111008	1"	1/2
RACG11111010	1"	5/8
RACG11111210	1" 3/16	5/8
RACG11111212	1" 3/16	3/4
RACG11111612	1" 7/16	3/4
RACG11111616	1" 7/16	1"

**MACHO FIJO ORFS / ORFS STUD MALE /  
MÂLE FIXE ORFS**



Ref.		
RACG11130404	9/16	1/4
RACG11130606	11/16	3/8
RACG11130806	13/16	3/8
RACG11130808	13/16	1/2
RACG11131008	1"	1/2
RACG11131010	1"	5/8
RACG11131210	1" 3/16	5/8
RACG11131212	1" 3/16	3/4
RACG11131612	1" 7/16	3/4
RACG11131616	1" 7/16	1"



CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION  
HIGH AND EXTREMELY HIGH CRIMPING FITTINGS  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**

**SISTEMA GAZ / GAZ METRIC SYSTEM / METRIQUE GAZ**



**HEMBRA GIRATORIA MÉTRICA GAZ / GAZ METRIC SWIVEL  
FEMALE / FEMELLE TOURNANTE MÉTRIQUE GAZ**



Ref.	∅		
RACG11012005	13	20x150	5/16
RACG11012006	13	20x150	3/8
RACG11012408	17	24x150	1/2
RACG11013010	21	30x150	5/8
RACG11013612	21	36x150	3/4
RACG11014516	33	45x150	1"



**HEMBRA GIRATORIA 90° MÉTRICA GAZ / 90° GAZ METRIC  
SWIVEL FEMALE / FEMELLE TOURNANTE 90° MÉTRIQUE GAZ**



Ref.	∅		
RACG11052006	13	20x150	3/8
RACG11052408	17	24x150	1/2
RACG11053010	21	30x150	5/8
RACG11053612	27	36x150	3/4
RACG11054516	33	45x150	1"

**MACHO FIJO GAZ / GAZ STUD MALE / MÂLE FIXE GAZ**





Ref.	∅		
RACG11032005	13	20x150	5/16
RACG11032006	13	20x150	3/8
RACG11032408	17	24x150	1/2
RACG11033010	21	30x150	5/8
RACG11033612	27	36x150	3/4
RACG11034516	33	45x150	1"

**SISTEMA ORFS / ORFS SYSTEM / ORFS SYSTEM**



**HEMBRA GIRATORIA ORFS / ORFS SWIVEL FEMALE /  
FEMELLE TOURNANTE ORFS**



Ref.		
RACG11110404	9/16	1/4
RACG11110606	11/16	3/8
RACG11110806	13/16	3/8
RACG11110808	13/16	1/2
RACG11111008	1"	1/2
RACG11111010	1"	5/8
RACG11111210	1" 3/16	5/8
RACG11111212	1" 3/16	3/4
RACG11111612	1" 7/16	3/4
RACG11111616	1" 7/16	1"

**MACHO FIJO ORFS / ORFS STUD MALE /  
MÂLE FIXE ORFS**





Ref.		
RACG11130404	9/16	1/4
RACG11130606	11/16	3/8
RACG11130806	13/16	3/8
RACG11130808	13/16	1/2
RACG11131008	1"	1/2
RACG11131010	1"	5/8
RACG11131210	1" 3/16	5/8
RACG11131212	1" 3/16	3/4
RACG11131612	1" 7/16	3/4
RACG11131616	1" 7/16	1"

CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION**  
**HIGH AND EXTREMELY HIGH CRIMPING FITTINGS**  
**CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**



**HEMBRA GIRATORIA 90° ORFS / 90° ORFS SWIVEL FEMALE /  
FEMELLE TOURNANTE 90° ORFS**



Ref.		
RACG11150404	9/16	1/4
RACG11150606	11/16	3/8
RACG11150806	13/16	3/8
RACG11150808	13/16	1/2
RACG11151008	1"	1/2
RACG11151010	1"	5/8
RACG11151210	1" 3/16	5/8
RACG11151212	1" 3/16	3/4
RACG11151616	1" 7/16	1"

**HEMBRA GIRATORIA 45° ORFS / 45° ORFS SWIVEL FEMALE /  
FEMELLE TOURNANTE 45° ORFS**



Ref.		
RACG11160404	9/16	1/4
RACG11160606	11/16	3/8
RACG11160806	13/16	3/8
RACG11160808	13/16	1/2
RACG11161008	1"	1/2
RACG11161010	1"	5/8
RACG11161210	1" 3/16	5/8
RACG11161212	1" 3/16	3/4
RACG11161616	1" 7/16	1"


**A3 SISTEMA SECO 4 Y 6 SPIRALES / 4 AND 6 SPIRAL A3 SYSTEM DRY /  
A3 SYSTEME SÈCHE A SERTIR 4 ET 6 TRESSSES**

**CASQUILLOS SISTEMA A3 / FERRULES A3 SYSTEM / JUPES SYSTEME A3**



**A3N4 CASQUILLO NO PELAR 4SP/H-R12 / A3N4 NO-SKIVE  
FERRULE 4SP/H-R12 / A3N4 JUPE S/DENUDAGE 4SP/H-R12**



Ref.	Type	
RACA3N412	R12-4SH-R13-R15	3/4
RACA3N416	R12-4SH-R13-R15	1"
RACA3N420	R12-4SH	1" 1/4
RACA3N424	R12-4SH	1" 1/2
RACA3N432	R12-4SH	2"


**CASQUILLO A3N6 NO PRECISA PELADO EXTERNO / NO-  
SKIVE FERRULE R13-R15 A3N6 / JUPE A3N6 SANS DENU-  
DAGE R13-R15**



Ref.
RACA3N620
RACA3N624
RACA3N632

**CASQUILLO A3S6 PRECISA PELADO EXTERNO / OUTER SKI-  
VE A3S6 FERRULE / JUPE A3S6 DENUDAGE EXT. R13-R15**



Ref.	Type	
RACA3S620	R13 - R15	1" 1/4
RACA3S624	R13 - R15	1" 1/2
RACA3S632	R13 - R15	2"





CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION  
HIGH AND EXTREMELY HIGH CRIMPING FITTINGS  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**

**SISTEMA SAE JIC / SAE JIC SYSTEM / SAE JIC**



**HEMBRA GIRATORIA SAE JIC / SAE JIC SWIVEL FEMALE /  
FEMELLE TOURNANTE SAE JIC**



Ref.		
RACA30411212	1" 1/16	3/4
RACA30411612	1" 5/16	3/4
RACA30411616	1" 5/16	1"
RACA30412016	1" 5/8	1"
RACA30412020	1" 5/8	1" 1/4
RACA30412420	1" 7/8	1" 1/4
RACA30412424	1" 7/8	1" 1/2
RACA30413232	2" 1/2	2"



**HEMBRA GIRATORIA 90° SAE JIC / 90° SAE JIC SWIVEL  
FEMALE / FEMELLE TOURNANTE 90° SAE JIC**



Ref.		
RACA30451212	1" 1/16	3/4
RACA30451612	1" 5/16	3/4
RACA30451616	1" 5/16	1"
RACA30452016	1" 5/8	1"
RACA30452020	1" 5/8	1" 1/4
RACA30452420	1" 7/8	1" 1/4
RACA30452424	1" 7/8	1" 1/2



**MACHO FIJO SAE JIC / SAE JIC STUD MALE /  
MÂLE FIXE SAE JIC**



Ref.		
RACA30431212	1" 1/16	3/4
RACA30431612	1" 5/16	3/4
RACA30431616	1" 5/16	1"
RACA30432016	1" 5/8	1"
RACA30432020	1" 5/8	1" 1/4
RACA30432424	1" 7/8	1" 1/2

**HEMBRA GIRATORIA 45° SAE JIC / 45° SAE JIC SWIVEL  
FEMALE / FEMELLE TOURNANTE 45° SAE JIC**





Ref.		
RACA30461212	1" 1/16	3/4
RACA30461612	1" 5/16	3/4
RACA30461616	1" 5/16	1"
RACA30462016	1" 5/8	1"
RACA30462020	1" 5/8	1" 1/4
RACA30462424	1" 7/8	1" 1/2
RACA30463232	2" 1/2	2"

**METRICO SERIE PESADA / METRIC HEAVY SERIES / METRIQUE SERIE LOURDE**



**HEMBRA GIRATORIA MÉTRICA SERIE PESADA O-RING /  
METRIC SWIVEL FEMALE O-RING HEAVY SERIES / FEMELLE  
TOURNANTE MÉTRIQUE SÉRIE LOURDE O-RING**



Ref.	∅		
RACA30913012	20	30x200	3/4
RACA30913612	25	36x200	3/4
RACA30913616	25	36x200	1"
RACA30914216	30	42x200	1"
RACA30914220	30	42x200	1" 1/4
RACA30915220	38	52x200	1" 1/4
RACA30915224	38	52x200	1" 1/2

**MACHO FIJO MÉTRICO SERIE PESADA O-RING / METRIC  
STUD MALE O-RING HEAVY SERIES / MÂLE FIXE MÉTRIQUE  
SÉRIE LOURDE O-RING**



Ref.	∅		
RACA30933012	20	30x200	3/4
RACA30933612	25	36x200	3/4
RACA30933616	25	36x200	1"
RACA30934216	30	42x200	1"
RACA30934220	30	42x200	1" 1/4
RACA30935220	38	52x200	1" 1/4
RACA30935224	38	52x200	1" 1/2





CONEXIONES PRENSAR ALTA ALTISIMA PRESION / HIGH AND EXTREMELY HIGH CRIMPING FITTINGS /  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION

**CONEXIONES PRENSAR ALTA ALTISIMA PRESION  
HIGH AND EXTREMELY HIGH CRIMPING FITTINGS  
CONNEXIONS A SERTIR HAUTE/ TRES HAUTE PRESSION**



**HEMBRA GIRATORIA 90° SERIE PESADA O-RING /  
90° SWIVEL FEMALE O-RING HEAVY SERIES /  
FEMELLE TOURNANTE 90° SÉRIE LOURDE O-RING**



Ref.	Ø		
RACA30953012	20	30x200	3/4
RACA30953612	25	36x200	3/4
RACA30953616	25	36x200	1"
RACA30954216	30	42x200	1"
RACA30954220	30	42x200	1" 1/4
RACA30955220	38	52x200	1" 1/4
RACA30955224	38	52x200	1" 1/2

**HEMBRA GIRATORIA 45° SERIE PESADA O-RING /  
45° SWIVEL FEMALE O-RING HEAVY SERIES /  
FEMELLE TOURNANTE 45° SÉRIE LOURDE O-RING**





Ref.	Ø		
RACA30963012	20	30x200	3/4
RACA30963612	25	36x200	3/4
RACA30963616	25	36x200	1"
RACA30964216	30	42x200	1"
RACA30964220	30	42x200	1" 1/4
RACA30965220	38	52x200	1" 1/4
RACA30965224	38	52x200	1" 1/2

**ORFS**



**HEMBRA GIRATORIA ORFS /  
ORFS SWIVEL FEMALE /  
FEMELLE TOURNANTE ORFS**



Ref.		
RACA31111012	1"	3/4
RACA31111212	1" 3/16	3/4
RACA31111612	1" 7/16	3/4
RACA31111616	1" 7/16	1"
RACA31112016	1" 11/16	1"
RACA31112020	1" 11/16	1" 1/4
RACA31112424	2"	1" 1/2



**HEMBRA GIRATORIA 90° ORFS /  
90° ORFS SWIVEL FEMALE /  
FEMELLE TOURNANTE 90° ORFS**



Ref.		
RACA31151212	1" 3/16	3/4
RACA31151612	1" 7/16	3/4
RACA31151616	1" 7/16	1"
RACA31152016	1" 11/16	1"
RACA31152020	1" 11/16	1" 1/4
RACA31152424	2"	1" 1/2



**MACHO FIJO ORFS /  
ORFS STUD MALE /  
MÂLE FIXE ORFS**



Ref.		
RACA31131212	1" 3/16	3/4
RACA31131612	1" 7/16	3/4
RACA31131616	1" 7/16	1"
RACA31132016	1" 11/16	1"
RACA31132020	1" 11/16	1" 1/4
RACA31132420	2"	1" 1/4
RACA31132424	2"	1" 1/2

**HEMBRA GIRATORIA 45° ORFS /  
45° ORFS SWIVEL FEMALE /  
FEMELLE TOURNANTE 45° ORFS**



Ref.		
RACA31161212	1" 3/16	3/4
RACA31161612	1" 7/16	3/4
RACA31161616	1" 7/16	1"
RACA31162016	1" 11/16	1"
RACA31162020	1" 11/16	1" 1/4