

CONEXIONES PRENSAR ALTA Y ALTÍSIMA PRESIÓN HIGH AND EXTREMELY HIGH CRIMPING FITTINGS CONNEXIONS À SERTIR HAUTE ET TRÈS HAUTE PRESSION

MANGUERA Y CONEXIONES DE CONTROL / HOSE AND CONTROL FITTINGS TUYAU ET CONNEXIONS DE CONTRÔLE


MANGUERA TS8 / HOSE TS8 / TUYAU TS8



Ref.			
MAN00702E	1/12	630	1.890


HEMBRA GIRATORIA BSPP 60° / 60° BSPP SWIVEL FEMALE / FEMELLE TOURNANTE BSPP 60°



Ref.	
RACMH110002	1/8 BSP
RACMH110004	1/4 BSP


HEMBRA GIRATORIA BSPP PARA MANÓMETRO / BSPP SWIVEL FEMALE FOR PRESSURE GAUGE
FEMELLE TOURNANTE BSPP MANOMÈTRE



Ref.	
RACMH120004	1/4 BSP
RACMH120008	1/2 BSP

HEMBRA GIRATORIA TOMA PRESIÓN / SWIVEL FEMALE PRESSURE CONNECTION
FEMELLE TOURNANTE PRISSE PRESSION



Ref.	
RACMH131615	16x150
RACMH131620	16x200