

Puntas de repuesto para soldadora
ST=Recta // ANG=Curvadas



3225

	g		
st	1	322510300	
ang	1	322510400	
st	1	322510500	
ang	1	322510600	
ang	1	322510700	
st	1	322510800	

Puntas de repuesto para soldadora



326010

	g		
5	1	326010200	
5	1	326020200	
5	1	326030200	

Puntas de repuesto para soldador 3270
SH1=redondo 0,5mm; SH2=plano 2mm; SH3=plano 3mm; SH4=plano 4mm



327020500-SH

0,5mm	1	327020500-SH1	
2mm	1	327020500-SH2	
3mm	1	327020500-SH3	
4mm	1	327020500-SH4	

Puntas de repuesto, forma cincel y lapiz



3295

	g		
5	1	329500350	
5	1	329500450	

Puntas de repuesto



3296

	g		
10	1	329600100	
10	1	329600200	

Bomba para des-soldar



3280

	g		
58	1	328000000	

Soldadura libre de plomo (Sn)
Ø 0.8 mm



3290

	L		
2000	1	329000330	
4000	1	329000500	

HERRAMIENTAS PARA MECÁNICA DE PRECISIÓN

Punzones en miniatura, ganchos y picos



2633/

	mm		
17 x 80 x 150 mm	12	2633/S4	
12 x 12 x 275 mm	12	2633L/S4	

Gancho doble para hilos y muelles



5418

	L		
145	1	5418	

Juego de ganchos para hilos y muelles



5419/6T

	mm		
5 x 78 x 110 mm	1	5419/6T	



Tenedor para desoldar

ergo®



BE-3529



197



5 BE-3529

Pinza pelacables lacada



2530-32/2530-40



130



5 2530-40

Dedo flexible con garras



2509



555



50 2509

Destornillador de ajuste con guía



5550



140

140



10 5550-3.2

5 5550-4.5

Rasqueta de acero al carbono



2487



210



12 2487

Pinza pelacables lacada



2530



605 mm



1 2530

Útiles de sintonización



5551-5554



220

205

195

180



1 5551

1 5552

1 5553

1 5554

Rasqueta triangular



3524



24

5



1 3524

1 3524L-K

Lupa 10 aumentos



3046-OP



105



12 3046-OP

Juego de útiles de sintonización



5600/4



75



1 5600/4

Rasqueta triangular



3525HB



168



5 3525HB

5551, 5552, 5553, 5554

BAHCO